AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT					CONTRACT ID CODE	PAGE	OF PAGES
2. AMENDME	NT/MODIFICATION NO.	3. EFFECTIVE	DATE	4. REG	UUISITION/PURCHASE REQ. NO.	5. PROJECT	NO. (If applicable)
A0005		01/05/20	006				
6. ISSUED BY	CODE	DTS-852		7. ADI	MINISTERED BY (If other than Item 6)	CODE DT	'S-852
U.S. DOT/RITA/Volpe Center 55 Broadway Cambridge MA 02142				U.S. DOT/RITA/Volpe Center 55 Broadway Cambridge MA 02142			
8. NAME AND ADDRESS OF CONTRACTOR (No., street, county, State and ZIP Code)				(x) 9A. AMENDMENT OF SOLICITATION NO. DTRT57-06-R-20003 9B. DATED (SEE ITEM 11) 11/22/2005 10A. MODIFICATION OF CONTRACT/ORDER NO.			
CODE FACILITY CODE			DE	- 105.5.1.25 (022.1.2.1.1.7)			
				IENDM	ENTS OF SOLICITATIONS		
separate let THE PLACE virtue of this reference to	ter or telegram which includes a reference E DESIGNATED FOR THE RECEIPT OF amendment you desire to change an offe the solicitation and this amendment, and TING AND APPROPRIATION DATA (If re-	to the solicitation OFFERS PRIOR or already submit or received prior quired)	n and amendment numbe TO THE HOUR AND DA ted, such change may be to the opening hour and o	ers. FA TE SPI made I	ceipt of this amendment on each copy of the off ILLURE OF YOUR ACKNOWLEDGEMENT TO ECIFIED MAY RESULT IN REJECTION OF YO by telegram or letter, provided each telegram o ecified. DIFIES THE CONTRACT/ORDER NO. AS DESC	BE RECEIVE DUR OFFER. r letter makes	D AT If by
CHECK ONE	A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT ORDER NO. IN ITEM 10A. B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation date, etc.) SET FORTH IN ITEM 14, PURSUANT TO THE AUTHORITY OF FAR 43.103(b).						
	C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF: D. OTHER (Specify type of modification and authority)						
E. IMPORTAN	T: Contractor is not.	is required t	o sign this document and	return	copies to the issuing	office.	
		-			solicitation/contract subject matter where feasil		
Please in numbered The purpresponse incompleattached Please	note that the number d Amendments posted pose of this Amendme e to the RFP. Pleas ete and were the res d to this document.	ing of to on the North is to e note to ponses for this	chese official volpe Center of provide additional the responsive common	al A web ditipons nt N th	replaced with Amendme mendments is off when site. onal responses to ques es provided in Amendme o. A0002. The correct the submission of your retofore changed, remains unchanged and in fundame AND TITLE OF CONTRACTING OFFICE trabeth A. Segal	tions rnt No. respon	ed to the received in A0003 were ases are now sal.
15B. CONTRA	ACTOR/OFFEROR		15C. DATE SIGNED		UNITED STATES OF AMERICA		16C. DATE SIGNED
(Signature of person outhorized to sign)			.SO. DATE OIGHED		(Signature of Contracting Officer)		

DTRT57-06-R-20003 Amendment No. A0005 Page 2 of 3

1. The following questions, with corresponding answers, were received in response to the solicitation. Please note that some of these questions were answered in Amendment No. A0002 and are provided again for your information. In some cases, the questions have a revised answer:

A. Fire Alarm System Specifications, Section 13852

Question 1: Section 13852, 1.02.B.1.a. Complete fire alarm system point list (or copy of CSGM software database) to aid in determination of total available device points.

Answer: No software copy is available (Johnson Controls did the programming). The FAA has a hard copy on site.

Question 2: Section 13852, 1.02.B.1.b. Copy of original installation plans showing installed speaker tap settings for determination of available amplifier power requirements.

Answer: Yes, these plans are available.

Question 3: Section 13852, 1.02.B.1.j. Is the elevator un-safe annunciator (assumed to be firefighter's hat symbol) existing?

Answer: None found on site.

Question 4: Section 13852, 1.02.B.1.m. Please provide applicable model number of desired Addressable Radionics Radio Fire Alarm Transceiver. Is the purpose of radio panel replacement for reliability, compatibility, or additional signal information transmission? If additional signal transmission (above and beyond current fire alarm panel alarm, supervisory, and trouble conditions) is desired please specify type and quantity of signals for estimation of necessary fire panel control modules and programming.

Answer: The purpose of the new Addressable Radionics Transceiver is to take advantage of the new Class A system that will be utilized as well as to transmit point address information of the system to the main fire alarm control panel. There appears to be a new SAFECOM SC4000V Transceiver installed in the Base Building at the Main FACU that is capable of wirelessly transmitting addressable device information. Contractor to verify and notify the Volpe Center immediately if this is not the case.

Question 5: Section 13852, 1.02.B.1.m. Please provide applicable model number of existing Hickam AFB Fire Department Radio Fire Alarm Receiver for verification of communication protocol compatibility and additional signal capability.

Answer: The Fire Department appears to have a SAFECOM 4000 compatible Transceiver capable of wirelessly receiving addressable device information. Contractor to verify and notify the Volpe Center immediately if this is not the case. Additionally, the Contractor is to install and fully program an MDACT Communications Card in the Main Siemens MXLV FACU, and connect and properly program to transmit all addressable device information to the SAFECOM SC4000V Transceiver, including ATCT device information.

DTRT57-06-R-20003 Amendment No. A0005 Page 3 of 3

Question 6: Section 13852, 2.20. Please specify minimum fault isolator module installation locations (one fault isolator module per signaling line loop is assumed otherwise).

Answer: That is an appropriate assumption. One fault isolator module per signaling line loop is sufficient.

B. Fire Alarm System Drawings dated 10/28/05

Question 1: Sheet FLS-HNL8, Note A. Please identify current elevator service provider for coordination of elevator tie-in and operations. Hawaiian Pacific Elevator (HP Elevator) apparently is no longer in existence.

Answer: KONE Elevator, 239 Puuhale Road, Honolulu HI. Phone No.: (808) 845-3291.

Question 2. Sheet FLS-HNL8. No heat detector is shown in elevator machine room as required for elevator shunt trip operation per Section 13852, 2.06.B.

Answer: Install a new compatible heat detector below the suspended ceiling for shunt trip purposes.

Question 3: Sheet FLS-HNL10. Riser diagram shows existing stairwell smoke detectors on levels 2 through 8. Only level 4 has an existing stairwell smoke detector. Please clarify if new detectors will be required for this stairwell at all levels.

Answer: Detectors will need to be placed at all levels of the stairwell.

C. General Questions

Question 1: Reprogramming of the existing MXLV (addressable Siemens/Pyrotronics) fire alarm control panel will require that the panel owner, in this case the FAA, submit a written request to Siemens allowing for a non-installing system vendor to gain access to internal programming software. This procedure will take approximately six weeks to complete. Please verify that owner is willing to make this request. Application forms can be provided upon request.

Answer: The Owner understands the design intent and will request information as needed to accomplish the Statement of Work. Provide requests for necessary information immediately upon award of the Master Contract.

2. All other terms and conditions of the solicitation remain unchanged.